




Inspection Plan Number : *
 Collect Date : 1/1/2010 - 3/31/2010
 Product ID : *
 Operation No : ip
 Char No : *

Product Data Collection Summary by Operation Analysis

Outsource Manufacturing Inc.

Product ID : 111-10303-003_A/B - RF TOP ASSY
Operation No : IP - 111-10303-003_A/B
Insp Plan Number : 0000006
Data Collection Number : 0007955



Characteristic No./Name	Total # Samples	# In Conformance	% In Conformance
1 - Solder Quality	1	1	100.00
2 - Component Quality	1	1	100.00
3 - Wire Quality	1	1	100.00
4 - Label	1	1	100.00
5 - Hardware Quality	1	1	100.00
6 - Epoxy Quality	1	1	100.00
7 - General Cleanlines	1	1	100.00



Product Data Collection Summary by Operation Analysis


Outsource Manufacturing Inc.

Product ID : 48-500001-001_B/ND - Advanced Telemetry

Operation No : IP - 48-500001-001_B/ND

Insp Plan Number : 0000362

Data Collection Number : 0007064



Characteristic No./Name	Total # Samples	# In Conformance	% In Conformance
101 - Cleanliness	315	315	100.00
105 - Hardware	315	315	100.00
110 - Cosmetic	315	315	100.00
102 - Flash/Calibrate/Test	267	267	100.00
103 - Jumper Shunts Verification	315	315	100.00
104 - Components Defects	315	313	99.37
106 - Antena Properly Mounted	315	313	99.37
107 - XB Orientation	315	315	100.00
108 - Cover Orientation	315	315	100.00
109 - Connectors Installation	315	315	100.00



Product Data Collection Summary by Operation Analysis

Outsource Manufacturing Inc.

111 - Calibrated Units in bag	315	315	100.00
-------------------------------	-----	-----	--------



Product Data Collection Summary by Operation Analysis


Outsource Manufacturing Inc.

Product ID : 24-751900_5/1.1 - 1 LED, PCBA Assy w/ Pad and Pins, Coated

Operation No : IP - 24-751900_5/1.1

Insp Plan Number : 0000364

Data Collection Number : 0006101



Characteristic No./Name	Total # Samples	# In Conformance	% In Conformance
101 - Cleanliness	995	995	100.00
107 - Lead Protrusion	995	995	100.00
102 - Pin Header	995	995	100.00
103 - Solder quality	995	995	100.00
104 - Hardware (Thermal gasket)	995	995	100.00
108 - Dimensional Verification	995	995	100.00
109 - Cosmetic	995	995	100.00
110 - Component defects	995	993	99.80



Product Data Collection Summary by Operation Analysis


Outsource Manufacturing Inc.

Product ID : 18-70.010_ND/A-03 - ASSY,WESTERN PROCESSOR CARD

Operation No : IP - 18-70.010_ND/A-03

Insp Plan Number : 0000437

Data Collection Number : 0006071



Characteristic No./Name	Total # Samples	# In Conformance	% In Conformance
101 - Cleanliness	4,979	4,979	100.00
105 - Hardware	4,979	4,979	100.00
110 - Cosmetic	4,979	4,979	100.00
112 - Component defects	4,979	4,943	99.28
102 - Loose Sippers	4,979	4,979	100.00
113 - Leak Test	4,979	4,956	99.54



Product Data Collection Summary by Operation Analysis


Outsource Manufacturing Inc.

Product ID : 111-10252-002_5/6 - Band B RF Assy

Operation No : IP - 111-10252-002_5/6

Insp Plan Number : 0000519

Data Collection Number : 0006731



Characteristic No./Name	Total # Samples	# In Conformance	% In Conformance
101 - Cleanliness	25	25	100.00
102 - Temp Dot	25	25	100.00
105 - Hardware	25	25	100.00
106 - Solder Quality	25	25	100.00
107 - Lead Protrusion	25	25	100.00
110 - Cosmetic	25	25	100.00
112 - Component defects	25	25	100.00



Product Data Collection Summary by Operation Analysis


Outsource Manufacturing Inc.

Product ID : 111-10335-002_6/6 - Top Assy, DC Section,SSPA 0.5-2.5-50

Operation No : IP - Top Assy, DC Section, SSPA 0.5-2.5-50

Insp Plan Number : 0000692

Data Collection Number : 0006053



Characteristic No./Name	Total # Samples	# In Conformance	% In Conformance
101 - Cleanliness	50	50	100.00
103 - Labels	50	50	100.00
105 - Hardware	50	47	94.00
106 - Solder Quality	50	50	100.00
107 - Lead Protrusion	50	50	100.00
109 - Dimensional Verification	50	50	100.00
110 - Cosmetic	50	50	100.00
112 - Component defects	50	50	100.00



Product Data Collection Summary by Operation Analysis


Outsource Manufacturing Inc.

Product ID : 18-000652_ND/A-01 - KNF Cable Pump Assembly

Operation No : IP - 18-000652_ND/A-01

Insp Plan Number : 0000705

Data Collection Number : 0006288



Characteristic No./Name	Total # Samples	# In Conformance	% In Conformance
100 - Wire Length	16	16	100.00
101 - Hardware	16	16	100.00
102 - Labels	16	16	100.00



Product Data Collection Summary by Operation Analysis


Outsource Manufacturing Inc.

Product ID : 18-000153_ND/B-03 - Assy - Card Carrier

Operation No : IP - 18-000153_ND/B-03

Insp Plan Number : 0000709

Data Collection Number : 0006388



Characteristic No./Name	Total # Samples	# In Conformance	% In Conformance
100 - Hardware	1	1	100.00
101 - Sensor	1	1	100.00
102 - Press	1	1	100.00



Product Data Collection Summary by Operation Analysis


Outsource Manufacturing Inc.

Product ID : 18-000163_ND/A-05 - Assy - Thermal Block

Operation No : IP - 18-000163_ND/A-05

Insp Plan Number : 0000712

Data Collection Number : 0006387



Characteristic No./Name	Total # Samples	# In Conformance	% In Conformance
100 - Connectors Seated	1	1	100.00
101 - Tie Wraps	1	1	100.00
102 - Labels	1	1	100.00



Product Data Collection Summary by Operation Analysis


Outsource Manufacturing Inc.

Product ID : 18-000339_ND/A-03 - Assy - Display Front

Operation No : IP - 18-000339_ND/A-03

Insp Plan Number : 0000715

Data Collection Number : 0006557



Characteristic No./Name	Total # Samples	# In Conformance	% In Conformance
100 - Dimensions	1	1	100.00
101 - Labels	1	1	100.00
102 - Hardware	1	1	100.00
103 - Cosmetic	1	1	100.00



Product Data Collection Summary by Operation Analysis


Outsource Manufacturing Inc.

Product ID : 18-000570_ND/A-04 - Assy - Cable E-Keeper Relay

Operation No : IP - 18-000570_ND/A-04

Insp Plan Number : 0000718

Data Collection Number : 0006558



Characteristic No./Name	Total # Samples	# In Conformance	% In Conformance
101 - Hardware	1	1	100.00
102 - Dimensions	1	1	100.00
103 - Label	1	1	100.00



Product Data Collection Summary by Operation Analysis


Outsource Manufacturing Inc.

Product ID : 24-751900_8/1.1 - 1 LED, PCBA Assy w/ Pad and Pins, Coated

Operation No : IP - 24-751900_8/1.1

Insp Plan Number : 0000819

Data Collection Number : 0007677



Characteristic No./Name	Total # Samples	# In Conformance	% In Conformance
101 - Cleanliness	732	732	100.00
102 - Pin Header	732	732	100.00
103 - Solder quality	732	731	99.86
104 - Hardware (Thermal gasket)	732	732	100.00
107 - Lead Protrusion	732	732	100.00
108 - Dimensional Verification	732	732	100.00
109 - Cosmetic	732	732	100.00
110 - Component defects	732	730	99.73
111 - ICD Program	732	715	97.68



Product Data Collection Summary by Operation Analysis


Outsource Manufacturing Inc.

Product ID : 24-752000_8/1.1 - 3 LED, PCBA Assy w/ Pad and Pins, Coated

Operation No : IP - 24-752000_8/1.1

Insp Plan Number : 0000823

Data Collection Number : 0007811



Characteristic No./Name	Total # Samples	# In Conformance	% In Conformance
101 - Cleanliness	788	788	100.00
102 - Intelligent Light Programming	788	788	100.00
103 - Thermal Gasket	788	788	100.00
104 - Intelligent Light Current Testing	788	788	100.00
105 - Conformal Coating	788	788	100.00
106 - Solder Quality	788	788	100.00
107 - Lead Protrusion	788	788	100.00
109 - Dimensional Verification	788	788	100.00
110 - Cosmetic	788	788	100.00
112 - Component defects	788	770	97.72



Product Data Collection Summary by Operation Analysis


Outsource Manufacturing Inc.

Product ID : 18-000560_ND/A-04 - Lower Drawer Sensors Cable Assy

Operation No : IP - 18-000560_ND/A-04

Insp Plan Number : 0000851

Data Collection Number : 0007793



Characteristic No./Name	Total # Samples	# In Conformance	% In Conformance
100 - Labels	5	5	100.00
101 - Dimensions	5	5	100.00
102 - Hardware	5	5	100.00
103 - Wire Routing	5	5	100.00



Product Data Collection Summary by Operation Analysis


Outsource Manufacturing Inc.

Product ID : 18-000631_ND/A-03 - Lower Drawer Sensor Extension Cable Assy

Operation No : IP - 18-000631_ND/A-03

Insp Plan Number : 0000859

Data Collection Number : 0007792



Characteristic No./Name	Total # Samples	# In Conformance	% In Conformance
101 - Cleanliness	5	5	100.00
102 - Wires	5	5	100.00
103 - Labels	5	5	100.00
105 - Hardware	5	5	100.00
109 - Dimensional Verification	5	5	100.00
110 - Cosmetic	5	5	100.00
112 - Component defects	5	5	100.00



Product Data Collection Summary by Operation Analysis


Outsource Manufacturing Inc.

Product ID : 18-000571_ND/A-02 - ASSY, SHEET, DRAWER GUIDES

Operation No : IP - 18-000571_ND/A-02

Insp Plan Number : 0000863

Data Collection Number : 0007791



Characteristic No./Name	Total # Samples	# In Conformance	% In Conformance
101 - Cleanliness	10	10	100.00
109 - Dimensional Verification	10	10	100.00
110 - Cosmetic	10	10	100.00
112 - Component defects	10	10	100.00



Product Data Collection Summary by Operation Analysis


Outsource Manufacturing Inc.

Product ID : 18-000662_ND/A-02 - ASSY, INSULATOR, POLYURETHANE

Operation No : IP - 18-000662_ND/A-02

Insp Plan Number : 0000867

Data Collection Number : 0007827



Characteristic No./Name	Total # Samples	# In Conformance	% In Conformance
101 - Cleanliness	5	5	100.00
109 - Dimensional Verification	5	5	100.00
110 - Cosmetic	5	5	100.00
112 - Component defects	5	5	100.00



Product Data Collection Summary by Operation Analysis


Outsource Manufacturing Inc.

Product ID : 18-000541_ND/A-03 - Magnet Push Bar, Magnets

Operation No : IP - 18-000541_ND/A-03

Insp Plan Number : 0000871

Data Collection Number : 0007829



Characteristic No./Name	Total # Samples	# In Conformance	% In Conformance
101 - Cleanliness	5	5	100.00
105 - Hardware	5	5	100.00
110 - Cosmetic	5	5	100.00
112 - Component defects	5	5	100.00



Product Data Collection Summary by Operation Analysis


Outsource Manufacturing Inc.

Product ID : 18-000355_ND/A-04 - Assy - Front, Upper Drawer

Operation No : IP - 18-000355_ND/A-04

Insp Plan Number : 0000944

Data Collection Number : 0008186



Characteristic No./Name	Total # Samples	# In Conformance	% In Conformance
101 - Cleanliness	5	5	100.00
105 - Hardware	5	5	100.00
112 - Component defects	5	5	100.00